Printed on: 2/17/2013 11:43:07 AM

National Transportation Safety Board		NTSB I	D: DCA09MA0	27	Aircraft Registration Number: N200WQ			
FACTUAL REPORT ANIATION			ence Date: 02/12	2/2009	Most Critical Injury: Fatal			
			ence Type: Accid	dent	Investigated By: NTSB			
Location/Time								
Nearest City/Place	State Zi		Zip Code	Local Time	Time Zone			
Clarence Center	NY		14032	2017	EST			
Airport Proximity: Off Airport/Airstrip	rom Landing Facility: 7							
Aircraft Information Summary								
Aircraft Manufacturer			Model/Serie	s		Type of Aircraft		
BOMBARDIER INC	DHC-8-402		Airplane					
Revenue Sightseeing Flight: No	Air I	Medical Transpor						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: NTSB investigators traveled in support of this investigation and used data obtained from various sources to prepare this aircraft accident report. ***

The Safety Board's full report is available at http://www.ntsb.gov/publictn/A_Accl.htm. The Aircraft Accident Report number is NTSB/AAR-10/01.

On February 12, 2009, about 2217 eastern standard time, a Colgan Air, Inc., Bombardier DHC-8-400, N200WQ, operating as Continental Connection flight 3407, was on an instrument approach to Buffalo-Niagara International Airport, Buffalo, New York, when it crashed into a residence in Clarence Center, New York, about 5 nautical miles northeast of the airport. The 2 pilots, 2 flight attendants, and 45 passengers aboard the airplane were killed, one person on the ground was killed, and the airplane was destroyed by impact forces and a postcrash fire. The flight was operating under the provisions of 14 Code of Federal Regulations Part 121. Night visual meteorological conditions prevailed at the time of the accident.

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: DCA09MA027

Occurrence Date: 02/12/2009

AVIATION Occurrence Type: Accident												
Landing Facility/Approach Inf	formation											
Airport Name			Airport ID:	T A	irport Elevation	Rur	nway Used	Runwa	ay Lengtl	h	Runw	vay Width
Buffalo-Niagara International	BUF		Ft. MSL									
Runway Surface Type:												
Runway Surface Condition:												
II C												
Approach/Arrival Flown: ILS												
VFR Approach/Landing:												
Aircraft Information				_								
Aircraft Manufacturer BOMBARDIER INC			Model DHC						Serial I 4200	Number		
Airworthiness Certificate(s): Trans	sport											
Landing Gear Type: Tricycle												
Amateur Built Acft? No	·						LBS Numbe			er of Engines: 2		2
Engine Type: Turbo Prop	_	Engine Manufacturer: Model/Series: P&W CANADA PW150A								d Power: '1 HP		
- Aircraft Inspection Information				_								
Type of Last Inspection			Date of Las	Date of Last Inspection Time			ince Last Insp	ection		Airfram	ne Tot	tal Time
Continuous Airworthiness			02/2010					Hours				819 Hours
- Emergency Locator Transmitter (I	ELT) Information											
ELT Installed?/Type Yes /			ELT Opera	ıted?	≀ Yes	ELT Ai	ded in Locatin	g Accide	ent Site?	? No		
Owner/Operator Information				_								
Registered Aircraft Owner			Street A	Addr	ress 1689 NONCO	- NNAH	BLVD STE	111		_		
COLGAN AIR INC			City									Zip Code
			Street A		MEMPHIS	TN		38132-2111				
Operator of Aircraft			Ollock,	luui	555							
COLGAN AIR INC			City							State	е	Zip Code
Operator Does Business As: Conti	inental Connection	 n		—	IViaiiasas	То	perator Desig	nator Cc	de: NS			
- Type of U.S. Certificate(s) Held:	Tiomai Germana	<u>. </u>					<u> </u>			V / · ·		
Air Carrier Operating Certificate(s):	: Flag Carrier/Dom	nestic										
Operating Certificate:					Operator Certific	cate:						
Regulation Flight Conducted Under: Part 121: Air Carrier												
Type of Flight Operation Conducted	d: Scheduled; Dor	nestic;	Passenge	r Or	nly							
	1	FACTU	JAL REPC)RT	- AVIATION				•			Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA09MA027

Occurrence Date: 02/12/2009

AVIATION				Occurrence Type: Accident										
First Pilot	Information			•					'					
Name						City	ity				Sta	te	Date of Birth	Age
On File	On F	n File (File	On File	47					
Sex: M	Seat Occupied:					Cer	rtificat	e Numb	er: On File					
Certificate(s): Airline Transport														
Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/Glider/LTA: None														
Instrument R	Rating(s): Airpl	ane												
Instructor Ra	ating(s): None	Э												
Current Bien	nial Flight Revie	w? 12/2008	3											
Medical Cert	t.: Class 1	Medica	al Cert. Status	s: With Wai	vers/Limita	itions			1	Date of La	ast Me	edical E	xam: 08/2008	
- Flight Time	e Matrix	All A/C	This Make and Model	Airplane Airplane Single Engine Mult-Engine		Ni	ight Instrum		Instrume	ment Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		3263	110	312										
Pilot In Comr	mand(PIC)	1205	110	174		-			_		+			
Instructor									\rightarrow		+			
Instruction R		110	110			-					+			
Last 90 Days		51	51			1					+			
Last 24 Hour		0	0											
Seatbelt Use	ed? Yes	Shou	lder Harness	Used? Yes		•	Toxico	ology Pe	erform	ed? Yes		Se	cond Pilot? Ye	s
Flight Plan	n/Itinerary													
Type of Fligh	nt Plan Filed: IF	R												
Departure Po	oint				•		State Airp		Airport Identifier		Departure Time		Time Zone	
Newark							NJ EW		EWR		2119		EST	
Destination							State		Airpoi	rt Identifie	er			
Buffalo								NY BUF						
Type of Clea	arance: IFR													
Type of Airs	pace: Air Tra	ffic Control												
Weather Information														
Source of Wx Information:														
Company														
				FACTUAL	REPORT	- AVI	ATION	1						Page 3

National Transportation Safety Board FACTUAL REPORT

NTSB ID: DCA09MA027

Occurrence Date: 02/12/2009

	AVIATION	,	Occurrenc	Accider	nt									
Weather	Information													
WOF ID	Observation Time	WC	OF Elevation	on	WOF D	WOF Distance From Accid				Direction From Accident Site				
								5 NM						
BUF	2210	EST		Ft.	MSL	<u> </u>					65 Deg. Mag.			
Sky/Lowes	et Cloud Condition:						1100 Ft. AGL			Condition of Light: Night				
Lowest Cei	iling: Broken			2100 Ft.	AGL	Visib	ility:	3	SM	Alti	meter:	"Hg		
Temperatu	ıre: °C [°C	Weath	her Condi	litions								
Wind Direc	ztion: 250	Wind Sp	peed: 15)		Wind	d Gusts:							
Visibility (R	RVR): Ft.	Visibility	/ (RVV)		SM	<u> </u>								
Precip and	/or Obscuration:													
Accident	Information													
Aircraft Dar	mage: Destroyed			Aircraft Fire: Ground					Aircraft Exp	losio	n Ground			
7 111 01 01 11 11 11									7	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	. 0104.14			
- Injury Sur	mmary Matrix	Fatal	Serious	Minor	ır	None	TOTAL							
First Pil		1		+	+	1100	1							
Second		1		+	+		1							
Student				+-	+		1	1						
	nstructor							1						
Check F	Pilot				\neg									
Flight E	Engineer													
Cabin A	Attendants	2		1			2							
Other C	Crew													
Passen	igers	45					45							
- TOTAL A	ABOARD -	49					49							
Other G	Fround	1					1							
- GRAND	TOTAL -	50					50							

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DCA09MA027

Occurrence Date: 02/12/2009

Occurrence Type: Accident

Administrative	Ini	form:	ation
Administrative			auoi

Investigator-In-Charge (IIC)

Effie Lorenda Ward

Additional Persons Participating in This Accident/Incident Investigation:

chris Soucy FAA

Washington, DC

pete frey ALPA

Mike Crook Colgan

Jim Davis NATCA

Deb Tortora Steelworkers Union - flight attendants union

Don Enns TSB - Canada

Julian Firth AAIB

Alan Thorne AAIB